



FLETCHER CREEK IMPROVEMENT DISTRICT

RR2, Site 3, Comp 38
Kaslo, BC V0G 1M0

Website: www.fletchercreekwater.com
Email: fletchercreekwater@gmail.com

Maintenance Report

December 13, 2018

Submitted by: Lance McLaren

Report:

1. Water Testing:

Test results for Nov and Dec have been circulated via email to the board and published on the website.

2. Water Intake Volume:

A decreased water volume has been notice at the intake. In the past week there has been a significantly lower volume than normally for this time of year. The concern is that a greater volume of water is being diverted for the Scarlett's hydro system.

The concern is if we were to experience a cold snap, given the lower creek volume, it could freeze entirely leaving FCID without water.

There is a question as to who has legal priority for water access and how best to communicate with Scarletts.

Board Action Required:

There is no additional action required from the Board